



Report No: SCR096S-027

			. toport ito:	00110000	<u></u>
1.		SCR096S-027			
2.					
	-	()			
	-	467 - 12	24		
	-	2009.06.09 - 2009.06.09			
3.					
	-	()			
	-	467-12	24		
4.					
5.					
	-	Ethernet Switch			
	-	Premier 2608A			
	-	220 V~ 60 Hz			
	-	-			
6.	1				
7.					
	-	25.0			
	-	50 % R.H.			



- 가

As a test result of sample which was submitted from the client, this test report dose not guarantees the whole product quality.

The test report should not be used for public relations, advertisement, conduct propaganda and raised for a suit without a written agreement of testing institute, and should not be used for various purposes besides subscribed use, and is valid for 90 days from date of issue.

The copy of this test report is invalid for use.

۶۱۰ مرود المعالم المارة الموادد المارة الم

This test report including test result conducted by using the test method which was suggested from a client.

2009 06 09

799 가 702

TEL.(031)420-5680 FAX.(031)420-5685



Report No: SCR096S-027

- (

- : 220 V~ 60 Hz - : U9024A - : Premier 2608A

(V)	(W)	(mA)	(Wh)	(Var)	(VA)	(PF)
198 V~ 60 Hz	9.63	107	9.72	18.65	20.97	0.459
220 V~ 60 Hz	9.92	101	9.90	20.08	22.40	0.443
242 V~ 60 Hz	9.88	97	9.86	21.82	23.94	0.412

1,

2, 가 .

3, 1 1 .

-



compliance
Report No: SCR096S-027

)

: 242 V~ 60 Hz : 1.1

: Premier 2608A

가

2,

	1	(mA)	(mA)			
Live to Output	On	0.12	3.5	Class I		
Live to Output	Off	0.17	3.5	Class I		
Neutral to Output	On	0.12	3.5	Class I		
Neutral to Output	Off	0.17	3.5	Class I		
1,	·					



compliance

Report No: SCR096S-027

Setting

